



Maddox ECE Construction Report

April 23, 2018



Preparing East wing for floor slab.



Looking West, rebar placed for columns.



Looking North across Central body.



Underground conduit from electrical room.



Mock up wall progression.