




South Elevation – Main Entrance; Concrete work continues and installation of light poles.

Southwest Corner of Property (Future Drive Aisle and Parking Lot) – Grading continues and installation of light poles.





Grand Hall – East Facing View; Light pendants newly installed.






South Classroom Wing (L1) – Flooring to be installed soon.

South Classroom Wing (L1) – Classroom; Floor being installed. Carpet install nearly complete.





being installed.

1

North Classroom Wing (L1) – Carpet install continues. Tack boards newly installed.

North Classroom Wing (L1) – Classroom; Flooring complete. Tack and white boards newly installed.

## **CBRE CAFETERIA**, COMMONS & NORTH CLASSROOM WING (L1)



North Classroom Wing (upper level) – Tack and white boards newly installed.

North Classroom Wing (upper level) – Classroom: Tack and white boards newly installed.

