


Maddox ECE Construction Report May 29, 2018






East Wing





West wing.





West wing and central body.





Steel studs on site to starting framing.





Central body, looking at main entrance area.





Looking North across central body. Decking installed.

