



Maddox ECE Construction Report
August 13, 2018



Aerial view

Main entrance from interior.




East side of building with siding installed.





View of East wing.

East wing interior.





Central body exterior.