



Cherrelyn Construction Report

February 12, 2019





South Elevation – Exterior Wall construction





South East Corner Elevation



Dining Commons Elevation



Main Corridor – Looking West



Library – Looking West



Administration Offices - Drywall

Northwest Corner - Exterior

