



Maddox ECE Construction Report

June 4, 2018



Entire building.





West wing. Exterior framing has started.



Rain chain foundations being formed.



Installing steel frame for skylight.



Central body, looking at main entrance area.



Looking North across central body. Plumbing trenches underway.