



Maddox ECE Construction Report

June 18, 2018



Aerial view of building with roof deck.





East wing exterior.



East wing.



West wing.



Central body looking south at main entrance.



Central body, looking at main entrance area.