

Cherrelyn Construction Report December 26, 2018







CBRE North Wing/Gym

Gym – North Elevation



Northwest Corner Exterior – Looking South

North Wing Courtyard



North wing – Southwest corner





Front Entrance



Center/South Wing – West Elevation (Windows are installed)





South Wing –Southeast corner



South Wing – East Elevation – Brick installed

