





South Elevation – Main Entrance; Sitework continues.



West Elevation – Sitework continues, concrete newly poured.



Grand Hall – North Facing View; Walkway panels newly installed, storefront frames on lower level and ceiling being installed and painting in progress.

Grand Hall – South Facing; Ceiling being installed and painting in progress.



Grand Hall – South Facing View; Ceiling being installed.






Gym – Flooring being taped for striping.

Admin/Teacher
Area – Flooring to
be installed soon
and painting in
progress.



South Classroom
Wing (L1) – Tile
recently
completed and
flooring to be
installed soon.





Cafeteria – Painting, mechanical, and electrical work continues.

North Classroom (L1) – Ceiling tile to be installed.



North Classroom Wing (L1) – Classroom; Ceiling tile to be installed.





North Classroom Wing (upper level) – Carpet newly installed and ceiling tile to be installed soon.

North Classroom Wing (upper level) – Classroom; Ceiling tile to be installed soon.



South Classroom Wing (upper level) – Flooring to be installed soon.