



CBRE Cherrelyn Construction Report November 20, 2018



North Wing – West Elevation Street View



West Elevation - East Elevation Street View





Center Hallway – looking East



Center Hallway Looking West



Front Door Entrance





Front Door -Looking South




South Elevation – Exterior Wall construction






South Wing – SE corner Exterior Wall Construction
















South Wing- Interior Wall Layout, HVAC Duct Installation



