





Front Entrance / Gym – Southeast Elevation; Brick, windows, and frames installation continues



Front Entrance – Southwest Elevation; Brick, roof and parapet installation continues



North Classroom Wing – Northwest Elevation; Brick, windows, and frames installation continues

Northeast Elevation; Brick installation continues







Grand Hall – South Facing View; Framing, mechanical, and electrical install continues

Grand Hall – North Facing View; Framing and drywall install continues



Grand Hall Main Entrance – North Facing View; Framing, mechanical, and electrical install continues

Grand Hall – South Facing View; Framing and drywall install continues







Gym – North Facing View; Windows and frames install continues




South Classroom Wing (lower level) – West Facing View; Framing, mechanical, electrical and plumbing install continues



Office Area – West Facing View; Framing, mechanical, and electrical install continues



Kitchen and Cafeteria – North Facing View – Framing and insulation install continues



Learning Commons – South Facing View – Framing install continues



North Classroom Wing (lower level) – West Facing View; Drywall complete and painting to begin soon





North Classroom Wing (upper level) – West Facing View; Drywall and HVAC installed; Drywall for soffit to begin



South Classroom Wing (upper level) – West Facing View; Framing, HVAC, install continues