

**Clayton School  
Construction Photos  
9.14.17**

**Foundation walls backfilled from SW corner through SE corner of gym. Damp-proofing continues around foundation**









**Courtyard is being closed in and final section of foundation will be poured week of 9/18**





**Fire Riser and Relocated Hydrant are in Place. Water Meter pit is underway.**

