



Cherrelyn Construction Report

December 17, 2018







North Wing – North Elevation



Gym – North Elevation



Gym – Interior (roof decking in place/
concrete floor complete



North Wing Interior – Wall framing has begun



Standing in Cafeteria – looking Northeast



Standing in Cafeteria – Looking Southeast (mechanical Yard)



Center Wing – North Elevation of Cafeteria Interior Wall



Standing in Cafeteria – Looking West



Center Hallway – Looking East



Center Hallway – Looking West