

**Clayton – Construction Photos
2.26.18**



Front Entrance / Gym – Southwest Elevation; brick and window frames being installed; roof and parapet installation continues



Plaza Area (Between Classroom Wings) – East Facing View; brick and window frames being installed; roof and parapet installation continues



North Classroom Wing – Northwest Elevation; brick, windows, and frames being installed; roof and parapet installation continues



East Elevation; brick, windows, and frames being installed; roof and parapet installation continues



Southeast Elevation; brick, windows, and frames being installed; roof and parapet installation continues



Grand Hall Main Entrance – North Facing View; framing and HVAC being installed




GYM – North View



South Classroom Wing (lower level) – West Facing View; framing and HVAC in progress




Grand Hall Main Entrance – North Facing View; framing in progress



Grand Hall Main Entrance – South Facing View; framing in progress



North Classroom Wing - Restrooms (lower level) – North Facing View; plumbing, framing and electrical install in progress



North Classroom Wing (lower level) – West Facing View; plumbing, framing and electrical install in progress



North Classroom Wing - Classroom (lower level) – plumbing, framing and electrical install in progress



Kitchen and Cafeteria – Northeast Facing View – plumbing, framing and electrical install in progress



Grand Hall – South Facing View; framing in progress



Learning Commons



North Classroom Wing (Upper level) – West Facing View; framing and electrical install in progress



North Classroom Wing – Classroom - (Upper level) – insulation and electrical install in progress



South Classroom Wing – (Upper level) –framing progress